

Foot operated workshop presses 40 - 50 tons



7 9

Accessories

61240



Shelves for storing.
(Excl. accessories shown on picture)



FP 40
FP 50

Foot operated for hands-free operation under load and return.



Fast and safe adjustment of the press table height.

	Model	Max (Ton)	(mm/stroke)	A (mm)	B (mm)	C (mm)	D (mm)	E (mm)	F (mm)	G (mm)	H (mm)	I (mm)	Kg
⑥	HP 40	40	6,7/0,7	840	840	200	300	125	60	1830	1350	620	315
⑦	FP 40	40	6,7/0,7	840	840	200	300	125	60	1830	1350	620	323
⑧	HP 50	50	6,7/0,7	840	840	200	300	125	60	1830	1350	620	315
⑨	FP 50	50	6,7/0,7	840	840	200	300	125	60	1830	1350	620	323
⑩	HP 60	60	3,8/0,4	850	1000	255	300	160	80	1980	1540	680	620
⑪	HP 70	70	3,8/0,4	850	1000	255	300	160	80	1980	1540	680	620
⑫	HP 100	100	3,4/0,3	900	1025	300	320	220	100	2150	1620	860	910

(Air operated height adjustment of press table on HP100 with chain attached to piston.)

Hand operated workshop presses 40 - 100 tons



Accessories

61100



Press plate.




Press punches.
(7 pieces, Ø12, 14, 16, 20, 22, 25, 30)



Bearing removal kit.
(4 pieces, Ø64, 67, 72, 75)



Winch for HP 100.
(Factory mounted)



Fast and safe adjustment of the press table height. (6 - 11)

Winch is available for HP 100 as a factory mounted accessory.



Moveable cylinder. (6 - 11)

Moveable cylinder is available for HP 100 as a factory mounted accessory.

